Wood De	stroying Insect Ins	pection Report	Notice: Please read	important consu	mer information on page 2.	
Section I. General Information Inspection Company, Address, & Phone			Company's Business Lic. No. 90059/95034		Date of Inspection 4/5/2018	
EXPRESS F 13521 West Cleveland,	EXPRESS PEST CONTROL 13521 West Ave. Down Cleveland, OH 44111 440-891-9411		Address of Property Inspected File Number: Purchaser = Shand 6239 Winter Foe Trail Lorain, OH 44053			
Inspector's Name, Signature, & Certification, Registration, or Lic. #				Structure(s) Ins	pected	
Michael Gould Michael O Hould			138967	House,Garaç	ge + shed Only	
Section II. Inspection Findings This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected: A. No visible evidence of a wood destroying insect infestation was observed. B. Visible evidence of a wood destroying insect infestation was observed as follows: 1. Live insects (description and location):						
2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location):						
3. Visible damage from wood destroying insects was noted as follows (description and location):						
NOTE: This is not a structural damage report. If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present. If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs. Yes No It appears that the structure(s) or a portion thereof may have been previously treated. Evidence of previous treatment: The inspecting company can give no assurances with regard to work by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.						
Section III. Recommendations No treatment recommended: (Explain if Box B in Section II is checked)						
Recommended treatment for the control of:						
:						
The following a Basement	Finished area-1-3-4 Unfinish	ted were obstructed or inaccess ned area-5-6-24		The inspector may write out obstructions or use the following optional key: 1. Fixed ceilings 13. Only visual access 2. Suspended ceiling 14. Cluttered condition		
☐ Crawispace ☑ Main Level				4. Floor		
Attic	5-11-13-24			5. Insula 6. Cabin	ation 17. Exterior siding tets or shelving 18. Window well covers	
☐ Garage ☐ Exterior	Attached 1-3-6, attic 5-11-13	Attached 1-3-6. attic 5-11-13-24			7. Stored items 19. Wood pile 8. Furnishings 20. Snow 9. Appliances 21. Unsafe conditions 10. No access or entry 11. Limited access 23. Synthetic stucco	
Porch Addition	Front stoop brick/cement 12. Rear stone steps 12			10. No ac 11. Limite		
☑ Other	shed-17-6			12. No ac	cess beneath 24. Duct work, plumbing, and/or wiring	
Section V.	Additional Comments a	and Attachments (these a	re an integral part of t	he report)		
Attachments _						
that all informa		refinancing. Seller acknowledge on, damage repair and treatmen	nt receipt of a cor	Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.		