ADDE	ENDUM: A		<u>-</u>
This is an Addendum to	the Purchase Agreement d	lated 10/27/2015	
for the purchase and sal	e of the Property known as	s (Street Address)	
•		, (City) <u>Cleveland</u>	
between Nicole Liambe	•		
and 2 toms llc			("SELLER")
		y said BUYERS and the SELI	,
Seller to repair broken glass Seller to repair broken glass Seller to re route down spou Seller to replace missing gut Seller to reroute 2nd floor bat Seller to flip (properly instal Seller to caulk half bath toile Seller to repair/replace show Seller to repair/replace vent Seller to replace the a/c insufficient of the seller to replace the seller to remain the buyer with much maintenance.	rand fistilisation in the crawl's block, remove non functional is away from home.Pg 10 er on south side of home. Pg11 th vent fan to the exterior of the insulation in the attic Pg 11 to secure toilet properly pg 1 er head in second floor bathrocovers on first floor (wood are ation tube.  h \$4000.00 toward a new furn	oace. Pg 7 vent and repair glass block. Pg 9  he home Pg 11  goom Pg 20 a) 2 noted, located on south wall.  ace and hot water tank. Both are on	their last life and require
Nicole Liambeis	dotloop verified 11/07/15 3:35PM EST		
BUYER	TTXC-UKZD-QTQR-QLXF	SELLER	DATE
BUYER	DATE	SELLER	DATE





ADI	<b>DENDUM:</b> inspection exten	tion	<u>÷</u>
This is an Addendum to	o the Purchase Agreement da	ated 10/27/2015	
	_	(Street Address)	
1318 W 76	• •	·	
		, (City) <u>Cleveland</u>	
between Nicole Liam	beis		("BUYER")
and 2 toms llc			("SELLER")
		s to 14 days after executed	
16 0 0 1 .	dotloop verified 11/03/15 8:27PM EST		
Nicole Liambeis BUYER	EC4P-HEWL-IUR3-TXXX  DATE	SELLER	DATE
BUYER	DATE	SELLER	DATE



