ADDENDUM B

This is a	n Addendum to the Purchase Agreement dated July 17	,,2	017,
for the p	urchase and sale of the Property known as (Street Address)	26760 Chapel Hill D	r.
	, (City) <u>Nor</u>		, Ohio,
between	Seth Bridger		_ ("BUYER")
and		("SELLER").	

The following is hereby mutually agreed upon by said BUYERS and the SELLERS:

1.) Install Sealed lid for Sump Pump and with Battery Backup.

2.) Fix Gas Leak in basement per Home Inspector report. Small gas leak in ceiling area pipes near

HVAC unit in basement. Buyer can provide picture from home inspector report to show location.

3.) Replace outdated components of Electrical Panel -- per Home Inspection Report

4.) Install GIF outlets installed in bathrooms, garage, basement, and outdoor patio area

(all outlets within 3 feet of water sources) per Home Inspection Report.

5). Address the insufficient HVAC duct work in the Family Room's Concrete Slab Foundation

that has been compromised by the three inch settling per Home Inspection Report.

6) Fix downspout on rear of house (above the eat in kitchen dining area) has been compressed and

compromises proper flow of rain water run-off. Request that the down spout be repaired to ensure

proper flow of water and functioning down spout.

7). Microwave to be in working order at time of possession.

8.) Detail paperwork on Plumbing Company used to snake the drainage tiles in May and June 2017

per disc. Contact information for Plumber most recently used.

9.) Provide garage door openers, window screens, and all instruction manuals for appliances.

10) Instructions on Home Security Alarm system and company.

11) Instructions on how the Gas Fire Place works.

			D 4 75
BUYER	DATE	BUYER	DATE
SELLER	DATE	SELLER	DATE
OLLER	DATE	OLLER	DATE